

CERA BARBOUR

PRODUCT DESCRIPTION:

Re-waxing treatment for “barbour” type garments

- Renews the garment and gives the original look as just re-waxed.

DIRECTIONS FOR USE:

Melt the product between 70 – 90 °C to make it perfectly liquid and evenly distribute it with a paintbrush. Finally hang the garment cool well and then leave stand at least 2 hours.

Warning: This product is dangerous, during heating use an appropriate ventilation (if necessary even a forced ventilation) and protect the operator with a mask with adequate filter to this product. Adopt the rules and national legislations to use this product.

LOGISTICAL INFORMATION:

Code	Packaging	Box	Pallet
A57-000D	1 kg	24 pcs.	-
A57-000H	5 Kg	4 pcs.	-

STORAGE: Keep the product in its original packaging at a temperature between 10 and 35 ° C and avoid any leakage of product. Avoid bitter cold and freezing. Do not expose to direct sunlight. It is advisable to preferably use the product within 18 months from production. For further information read the safety data sheet (SDS).

All the instructions provided are the result of studies and experiences acquired and they do not exempt the client from verifying the suitability of the products for the purposes of use. Therefore the application of the products and the results obtained must be considered independent from our responsibility.